

MIG Welding



Outcomes

1. Learn the basics of MIG Welding
 1. Hoses
 2. Regulators
 3. Cylinder storage
 4. Setting the flow regulator
 5. Selecting Amperage and Wire Feed Speeds
 6. Butt Joint
 7. Outside Corner Joint
 8. Tee Joint

We will cover

- **Safety Equipment**
- **MIG Welding**
- **Plasma cutting**

Notice

Protect your own safety.

You are responsible for verifying all information related to safety and protection measures.

You are responsible for damage to equipment and facilities.

(I believe that I am giving you accurate information but, *don't take my word for it. Independently verify for yourself.*)

Welding

Fusion of 2 (or more) pieces of metal by melting and joining.

(Plastic is also welded – but will not be discussed as part of this Workshop.)

Welding

What is a good weld.

A good weld starts with *clean* well aligned material

Smooth, non porous, as strong as or stronger than the metals being joined.

Full penetration (melted joint is all the way through the material)

Full fusion (materials are melted together, weld is not laying on top of the joined materials)

No 'inclusions' – non-metallic stuff, carbon, slag, bubbles, or other foreign materials in the weld.

Rusty metal makes lots of sparks and poor welds – rust gets combined in the weld. Rust is not strong.

Welding

Getting material clean.

Mill Scale – impurities that come to the surface when the metal is made.

Remove, rust, impurities, mill scale, oil, paint, platings, coatings.
(Be aware removing paint – may contain lead.)

When using silicon carbide – wear a dust mask !

Protective Gear

Clothing, cotton (Man made fabrics. Polyester, rayon, nylon, melt and stick to you)

Gloves (stuff is hot) Typically lighter than gas welding gloves

Long sleeves

Long pants

Shoes

Goggles / helmet

Head cover or Do Rag

Special welding garments

Galvanize/Platings

Don't weld Galvanized or Zinc plated metal. The fumes are very dangerous (Zinc Flu).

Cadmium and other platings are dangerous as well

Pot Metal (is a Zinc alloy) Pot metal is not MIG weldable.

Welding Space

Flamable objects (wood shavings, rags, fluids) in the welding shop area are subject to having hot metal set them on fire.

Typically your vision may be somewhat blocked by goggles or a hood, you may not be aware of a fire.

Protecting Others

MIG welding – bright arc light, flying sparks

Plasma cutting – Lots of flying sparks

Let people around you know what is going on. Let folks know you are striking an arc. Give them a chance to move to a safe area and shield their eyes. (Tell them to move if they don't take the hint.)

Pets. A cat or dog will stare at the arc until they go blind. Protect their vision. Move them out of sight of the welding operation.

UV

Arc welding produces a lot of UV (Ultra-Violet Rays)
Same ones that give you sunburn

Except

It will be the worst sunburn you ever had and it will
happen very quickly (single digit minutes)

Sunburned eyes are no fun at all and can cause
blindness.

For MIG welding, use a welding hood (full face
coverage).

Eye Protection

Operation	Electrode	Current	Minimum
Shielded metal arc welding = Stick = SMAW	Less than 3	Less than 60	7
	3 - 5	60-160	8
	5 - 8	160-250	10
	More than 8	250-550	11
Gas metal arc welding and flux cored arc welding = GMAW - MIG		Less than 60	7
		60-160	10
		160-250	10
		250-500	10
Gas tungsten arc welding – GTAW – TIG		Less than 50	8
		50-150	8
		150-500	10
Plasma arc cutting	(Light)**	Less than 300	8
	(Medium)**	300-400	9
	(Heavy)**	400-800	10
Torch brazing			3
Torch soldering			2

MIG GMAW

How it works

Feeds filler wire that also carries welding current through a gas shield

Wire comes from a roll inside the machine

2 controls – Power and wire feed speed

Make sure you have a good ground

Don't step on the cables

No sharp bends or kinks in the welding cable

Liners

MIG Pliers – special

Point and shoot

MIG GMAW

How it works

Short Circuit – wire carrying current touches material, gets very hot and melts both base material and wire.

Globular deposition – molten glob forms on end of wire and is moved to the base metal. Heat of glob melts material together.

Spray Transfer – Arc vaporizes wire before it gets to the base metal forming a spray of very hot liquid metal. Melts the base material. Needs special gun. Heavy material. More stick out. Flat and horizontal.

MIG Arc Temperature

Air is not a good conductor of electricity.

Arc jumps between electrode and the material to be welded in ionized gas. Arc is started by the current from the welder, through the wire, short circuiting and melting (vaporizing) the wire.

Temperature between 3,000° and 20,000° C
(5,400° F to 36,000° F)

Fume Extraction

Extract the fumes or provide lots of ventilation.

Fume extractors

Fans

The great outdoors

Shielding Gasses

Protect the weld from oxidizing (and nitrogen and hydrogen – embrittlement)

Argon (great general choice)

Helium (expensive, hot arc, higher flow rate, high current applications)

CO₂ (runs hot, inexpensive, less stable arc)

Mixtures – We have Argon/CO₂ and pure Argon (For Aluminum).

Al, Ti – use pure argon

Sometimes a fixture is used to supply shielding gas to the back side of a weld.

Flow of gas shields the weld through the 'gas lens' of the welding gun nozzle. Use about 20 CFH (cubic feet per hour) of gas flow

MIG GMAW Gasses

Typical Welding Parameters of Mild & Low Alloy TIG, MIG					
Process	Diameter of Wire		Voltage (V)	Amperage (A)	Shielding Gas
	Inches	Millimeters			
TIG (GTAW)	.035	0.9	10 – 12	50 – 70	100% Argon
	.045	1.14	10 – 12	70 – 100	
	1/16	1.6	12 – 15	100 – 125	
	3/32	2.4	15 – 20	125 – 175	
	1/8	3.2	15 – 20	175 – 250	
MIG (GMAW) Spray Transfer	.035	0.9	28 – 32	165 – 200	98% Argon + 2% Oxygen or 75% Argon + 25% CO ²
	.045	1.14	30 – 34	180 – 220	
	1/16	1.6	30 – 34	230 – 260	
MIG (GMAW) Short Circuiting Transfer	.035	0.9	22 – 25	100 – 140	100% CO ²
	.045	1.14	23 – 26	120 – 150	75% Argon + 25% CO ²

MIG welder




Fig. 27.1 Components of Gas Shielded Metal Arc Welding Process

Ground

This is critical for ALL Arc welding.

It is the return path for the electrical current.
Usually connected to the work or the metal table upon which
the work is located

Shiny surfaces make good grounds

You do not want to become the ground path.
Can be deadly.

(Oh, and stay out of the insides of the welders. Voltages and
currents inside the box are absolutely deadly.)

Any ARC Welding

Importance of Ground

Ground to the item if possible

Ground to metal table is next best – expect sticking – assumes your item has a metal to metal connection to the table (i.e. cannot be laying on an insulating surface – like a fire brick)

Includes Plasma cutting

MIG GMAW Wire

Types - e.g. ER70S-6

ER - Electric Rod

70 - This two or three-digit number represents the minimum tensile strength of the weld metal, measured in pounds per square inch (PSI) multiplied by 1,000.

S - Solid wire.

6 - This number (with sometimes a letter added) indicates chemical additives used in the wire which may effect the polarity setting on the machine.

The 6 in this case indicates more deoxidizers have been added to the wire, which is helpful when welding on dirty or rusty steel. The other general purpose carbon steel wire type is ER70S-3. This one doesn't have the added chemicals, so is used primarily on new or clean steel.

The most commonly used aluminum MIG wires are ER5056, a soft wire with good ductility, and ER5356, which is harder and has a high tensile strength.

Stainless steel MIG wire includes designations like ER308, ER316 and ER308-L. The L stands for low carbon, which provides extra corrosion resistance.

Fluxed

Aluminum – Uses spool gun

MIG FCAW Wire

Flux-Cored Wire

Using "cored" wire allows a MIG welder to skip the tank of CO₂ or argon and weld without the gas. That's because the wire core contains ingredients that do the job of shielding the weld pool. This is particularly helpful when welding out of doors, since a stiff breeze is enough to disperse a compressed gas. The process is formally known as Flux-Cored Arc Welding (FCAW).

Designations get complex. I.e. E71T-1C JH8

(Electrode 70,000 tensile, all position, tubular, rutile slag, CO₂ gas, less than 8ml of H₂ per 100g)

MIG GMAW

Polarity is DC (Direct Current)

May require reversing for flux coated or core wire

DCEP Direct Current Electrode Positive – most common

DCEN Direct Current Electrode Negative

AC (Alternating Current – not recommended)


MIG GMAW Wire

Wire comes in various diameters. Larger wires, larger welds. 0.025" 0.030" 0.035" 0.040"
Use drive wheels and tips that match the wire size










Fast
Easy (maybe too easy)

Spatter
Clogs nozzle and messes up shielding gas flow
(Nozzle dip or spray helps to prevent sticking)

MIG GMAW Wire

LINCOLN ELECTRIC 255XT POWER MIG		METAL THICKNESS												
Wire Type	WIRE SIZE [in.]	22 ga 0.030 in. (0.8mm)	20 ga 0.036 in. (0.9mm)	18 ga 0.048 in. (1.2mm)	16 ga 0.062 in. (1.6mm)	14 ga 0.075 in. (2.0mm)	12 ga 0.108 in. (2.8mm)	10 ga 0.136 in. (3.5mm)	3/16" 0.187 in. (4.8mm)	1/4" 0.250 in. (6.4mm)	5/16" 0.312 in. (7.9mm)	3/8" 0.375 in. (9.5mm)	1/2" 0.500 in. (12.7mm)	
	30-40 CFH	V / o/p	V / o/p	V / o/p	V / o/p	V / o/p	V / o/p	V / o/p	V / o/p	V / o/p	V / o/p	V / o/p	V / o/p	
MIG SuperArc [®] L-56 (DC-) 	75%/25% Ar/CO ₂	0.025	15/90	15/110	16/140	17/240	17/260	18/310						
		0.030	15/130	16/160	18/180	18/230	18/280	19/330	20/390	21/430				
		0.035			16/120	16/190	16/210	18/240	18/250	19/350	20/370	21/440	22/450	23/470 ¹
	100% CO ₂	0.045			17/80	17/110	17/140	19/160	19/170	19/180	25/200	26/230	26/230	28/240 ²
		0.025		18/170	19/190	19/210	19/260	20/315						
		0.030		18/140	19/150	19/210	19/220	20/240	21/260	22/280				
Gas-Shielded Outermix [®] 71M UltraCore [®] 71AB5 (DC-) 	75%/25% Ar/CO ₂	0.035					21/250	22/300	23/350	24/400	26/500			
		0.045					23/250	24/230	24/270	25/310	26/350			
	100% CO ₂	0.035					23/250	24/300	25/350	26/400	28/500			
		0.045					24/200	25/230	26/270	27/310	27/350			
Stainless BlueMax [®] 308 L38 (DC-) 	Tri-Mix 90%/7.5%/2.5% He/Ar/CO ₂	0.030			19/370	20/410	21/450	22/500	23/450	24/520	26/590			
		0.035				20/280	20/300	22/400	24/430	25/485	26/470	27/520		
Innershield [®] NR211-MP & 218 (DC-) 	100% Ar	0.035			14/70	14/80	15/90	16/100	16/110	16/120				
		0.045			14/70	15/80	16/90	16/100	17/100	18/110	18/120	19/130		
Aluminum SuperGlass [®] 4043 (DC+) 	100% Ar	0.030			15/340	16/370	17/430	25/480	25/500	27/560				
		0.035				15/270	16/335	20/375	23/590	24/620	25/700			
Aluminum SuperGlass [®] 6358 (DC+) 	100% Ar	3/64					20/300	22/300	23/360	24/430				
		0.035				16/380	16/475	18/570	18/580	21/600	22/620	23/700		
		3/64					18/350	21/300	22/310	23/330				

MIG GMAW Wire

											
Wire Type		30-40 CFH		WIRE SIZE (In.)	22 ga .030 in (0.8mm)	20 ga .036 in (0.9mm)	18 ga .048 in (1.2mm)	16 ga .060 in (1.5mm)			
		75%/25% Ar/CO ₂	0.025	15/90	15/110	16/140	17/240				
			0.030	15/130	16/160	18/190	18/230				
			0.035			16/120	16/190				
			0.045			17/80	17/110				
		100% CO ₂	0.025		18/170	19/190	19/210				
			0.030		18/140	19/150	19/210				
			0.035			17/130	18/150				
			0.045			17/120	17/130				

Stick Out

How much wire between the nozzle and the work.

Should be $\frac{3}{8}$ to $\frac{1}{2}$ inch.

Use MIG pliers to trim to length before starting the weld

The MIG Weld

Tends to be more 'proud' than gas or TIG welding due to the constant feed of wire into the weld puddle.

Inspection

Check the equipment for problems before you start.

General inspection

Valves work, connections tight

Hoses, no cracks, general condition

Gas cylinders, damage, upright, constrained

Regulators, connections tight

Hood lenses clean and in good shape, and adjusted for your head

Get Comfortable

Set up the work at a convenient height
Make it easy to move along the weld seam
If possible, be seated
Have a place to brace your arms/hands. Elbows in.

Welding uses lots of small moves and fine motor control

Arrange the hose so it is not pulling on the gun or uncomfortable.

Place welding on a suitable surface. Fire bricks are good. A welding table (avoid welding to the table).
Concrete is not a good welding surface (H₂O expands).
Confirm good ground.

Make a dry run – move the MIG gun along the weld path to be sure nothing binds up and that you have good access to the joint.

Cylinders

Keep upright (If laid down allow 30 minutes upright before using)

Cylinder cap when not in use

Argon CO2 (25% CO2, 75% Argon) 1,500 psi

Argon 2,640 psi

Secure tanks with chain.

Regulators

Remove protective cap

Visually Inspect

Look for any contamination on or in the gas outlets of both the bottle and regulator

Gauges should be up at slight angle.

Be sure regulator flow control valve is all the way open

Don't stand in front of regulators when opening valve.

Flow rate is in CFH (Cubic Feet per Hour)

Typical is 20- 25 CFH

Too low a flow results in a porous contaminated weld.

Too high a flow wastes gas.

These are all dry connections. (No oil, grease, pipe dope, Teflon tape, etc.)

Regulators

MIG Gun Nozzle Size Inside Diameter	Minimum Suggested Flow	Typical Flow Setting	Maximum Suggested Flow
3/8 inch (For Access on Small Welders)	15 CFH	18-22 CFH	~ 30 CFH
1/2 inch (Typical on Small Welders)	18 CFH	22-27 CFH	~ 40 CFH
5/8 inch (Most Industrial Welders)	22 CFH	30-35 CFH	~ 55 CFH
3/4 inch (For Large Size Cored Wire)	30 CFH	30-40 CFH	~ 65 CFH

Types of Joints


Types of Welding Joints



Butt Joint




Lap Joint




Corner Joint





Edge Joint



Tee Joint




Good Welds




Weld Preparation

Butt Joints - Edge Preparation & Weld Type



The Puddle



Pull vs. Push

Pull – narrower weld

Push – wider weld

Whichever – be sure you can see the puddle

See the puddle melting into the material

Plasma Cutting

So much nicer than Oxy/Acetylene

Is an ARC process

Uses 'DRY' air and and electric arc to make a VERY hot plasma stream. **45,000°F**

Has a very thin 'kerf'

Very little slag and easily removed

Typically start cuts at an edge, but can pierce (there's a technique)

Still makes lots of sparks.

Ground is very important –

(vid Weld 1)

Tacking

Tacking is making small welds around the piece to hold the pieces in position while the welding is done.

You are using lots of heat and metal expands quite a bit when heated.

The 'tack' welds hold everything in alignment and helps prevent warping.

Spatter

Particles of molten metal that are thrown out of the weld seam

Tends to build up inside the gun gas shield and can disturb the shielding gas lens (flow)

Excessive spatter – are you running out of shielding gas?

Nozzle spray or Dip helps to prevent and makes spatter easy to remove (For the gun only – don't put on material to be welded)

Spatter



Spatter



Aluminum

A spool gun is used for Aluminum

Spool of wire is located at the gun end instead of inside the machine

Must use pure Argon gas

Suitable for heavier aluminum (1/8 inch or more)

Coupons

We will make 3 welding 'coupons' (these are just sample test welds). Butt joint, outside/inside angle, and a tee joint.

Cutting your material

Cut 6 5-6 inch (or so) pieces using a plasma torch

Running your first bead

2 pieces of flat side by side.

Look for consistent width and height

Try to go in a straight line

Wait for the puddle to form

Just get used to the equipment

Adjust your welding position as needed

Your next Joint

Use 2 pieces of metal and a couple of magnets to make a piece of angle

2 pieces together, one slightly overlapping the other

'Tack' (weld it together a little at each end – this will hold the pieces together as you weld)

Remove the magnets

Weld the joint by moving the puddle along the joint

Flip over and weld the inside joint

(vid weld 1)

Third Coupon

A Tee Joint (a little more challenging)

Position material, tack, and weld

Weld both sides

(vid weld 2)

Tips

Puddle too hot

Metal drips through – holes form

Too cold

Weld material just laying on top, no fusion.

When welding a thick piece to a thin piece, concentrate the heat more on the thick piece.

To fill a hole, work from the edge in, jump around, don't try to fill the hole all at once from one side.

Listen to the sound (referred to as ripping fabric or frying bacon)

Please ask Questions

If you are not sure – Ask

Stewards are here to help you make better welds
(but not to do the welding for you)

There are special techniques and materials for
special circumstances.

There's a lot more to learn.

Biggest problems

Machine not set up correctly.

Not enough / too much heat (amperage)

Wire feed too fast or too slow

Too far from material (too much Stick Out)

Dirty materials

Poor penetration (weld just laying on top of material)

Welding your work to the welding table

Running out of shielding gas

Picking up *hot* parts

Be Safe

Be Safe.

Be Careful.

How do I get independent access to the Welding Shop?

At a future date you must find one of the welding shop stewards and prove Proficiency

You must show that you know the safety guidelines and equipment, how to turn on the shielding gas, adjust the flow, turn on the machine, set it for a particular material, perform a short test weld, and shut down the machine

You must also know where the fire extinguisher is (this is a pass/fail question)

Videos

https://www.youtube.com/watch?v=7_T2VVCnVI8

<https://www.youtube.com/watch?v=Xod-ByrxHg4>

Equipment



Lincoln Electric has kindly donated a wonderful set of modern superb quality equipment to our welding shop.

If you are considering purchase of an arc welder or plasma cutter, I can recommend Lincoln as a world class solution.